

ERRATA

“Symmetric Branching of Mode II and Mixed-Mode Fatigue Crack Growth in a Stainless Steel,” by Cai-Fu Qian, Ming-O Wang, Bao-Juan Wu, Shu-Ho Dai, and J. C. M. Li, published in the July issue of the JOURNAL OF ENGINEERING MATERIALS AND TECHNOLOGY, Vol. 118, pp. 356–361.

In the above paper, Fig. 1 (part b) on p. 357 was printed incorrectly. The correct version of Fig. 1 is printed below.




Fig. 1 Crack growth rates together with crack paths