

ERRATA

De Winter, A., and Blok, H., "Fling-Off Cooling of Gear Teeth," published in the February, 1974 issue of the Journal of Engineering for Industry, pp. 60-70.

The heading, "The Importance of Rapid Completion or Oil Coverage of Tooth Faces," on p. 61, 1st col., should read, "The Importance of Rapid Completion of Oil Coverage of Tooth Faces."

The unnumbered formula on p. 66, 1st col., in between formulas (27*b*) and (27*d*) should be assigned the number (27*c*) and be rewritten as follows,

$$0 < \varphi_{f1, tr} \leq \varphi_{f1} \leq 5 \quad (27c)$$

Formula (30*b*) on p. 66, 2nd col., should be rewritten as follows,

$$\frac{1}{E_r} = \frac{1}{2} \left[\frac{1 - \nu_1^2}{E_1} + \frac{1 - \nu_2^2}{E_2} \right] \quad (30b)$$