

ERRATA

We are sorry to report an error that has carried into the following two ASME papers:

Y. Elkassabgi and J. H. Lienhard, "Influences of Subcooling on the Burnout of Horizontal Cylindrical Heaters," ASME JOURNAL OF HEAT TRANSFER, Vol. 110, No. 2, 1988, pp. 479–486,

where it appears in Eqs. (19) and (21), and again in the abscissa of Fig. 8, and

J. H. Lienhard, "Burnout on Cylinders," ASME JOURNAL OF HEAT TRANSFER, 50th Anniversary Issue, Vol. 110, No. 4B, 1988, pp. 1271–1286,

where it appears in Eqs. (29) and (31), and again in the abscissa of Fig. 14.

In each case:

$Ja/Pe^{1/4}$ should be changed to $Ja/Pe^{1/2}$.