

Index

Page numbers followed by *f* and *t* refer to figures and tables, respectively.

a

- Abbé error, 75–76, 76*f*
- Abbé offset, 76
- Accelerometers, calibration of, 306–307, 307*t*, 308*f*
- Accreditation:
 - of calibration labs, 226–231, 227*f*–230*f*, 227*t*
 - and conformity assessment, 11, 12
- Accuracy:
 - of measurement, 2, 64
 - errors affecting, 240–241
 - in work pieces, 74–75, 74*f*, 75*f*
 - of observation, 108
 - of readings, 108
- Accuracy ratio, in calibration, 194
- Acoustic measurements:
 - calibration of instruments, 308
 - mechanical, 298–300, 299*f*, 300*f*
- Active error compensation, 80
- AFM, *see* Atomic force microscopy
- American wire gauge, 263, 264*f*
- Amount of substance, SI unit of, 4*t*, 9
- Ampere (A), 4*t*, 6, 9
- Analysis models, differences between number and, 104–105
- Angle gauges, 278, 279*f*
- Angle measurement, 276–281
 - face standard devices, 277–279, 278*f*, 279*f*
 - incline, 279–280, 279*f*, 280*f*
 - inclinometer, 279–280, 279*f*, 280*f*
 - spirit level, 279, 279*f*
 - line standard devices, 277, 277*f*
 - optical instruments for, 280–281, 281*f*
 - autocollimators, 281, 281*f*
 - optical angle comparators, 280–281, 281*f*
- Angle plate, 265, 265*f*, 266
- Angstrom (Å), 7*t*
- Angular conversions, 44–45, 45*t*
- Angular velocity (1/s), 5*t*
- Applied math and statistics, 39–60
 - angular conversions, 44–45, 45*t*
 - engineering notation, 39–40
 - formulation of standard uncertainty and
 - average of indirect measurements, 52–60
 - determining measured value and random error, 52
 - normal distribution, 53–55, 54*f*, 55*t*
 - repeated measurements of one single quantity, 52–53
 - Student's *t*-distribution, 55–56, 56*f*, 58–60, 58*f*
 - geometry, 44, 44*f*
 - areas, 44, 44*f*
 - perimeter, 44, 44*f*
 - volumes, 44, 44*f*
 - graphs and plots, 45–46, 46*t*
 - Imperial/metric conversions, 40–41, 40*t*–41*t*
 - linear interpolation, 42, 42*f*
 - number bases, 42–43
 - ratio, 41
 - rounding, 43
 - scientific notation, 39

- Applied math and statistics (*contd.*)
 - significant figures, 43
 - statistical analysis and common
 - distributions, 47–52
 - definition of measurement data, 47
 - formulation of mean and variance for
 - direct measurements, 49, 50
 - mean and variance based on samples, 50
 - probability, 48
 - sample and population, 49, 49f
 - standard deviation of the mean, 51, 51f
 - statistical analysis of measurements, 47–48
 - statistical measurements, 47
 - truncation, 43
 - Area, 44, 44f
 - Area chart with Zoom window, 46t
 - Arrow chart, 46t
 - ASME standards, 145–146
 - ASME symbols, 188
 - B46.1, 145
 - B89, 146
 - B89.1.2M, 146
 - B89.1.5, 145
 - B89.1.6, 145
 - B89.1.7, 146
 - B89.1.8, 146
 - B89.1.9, 145
 - B89.1.10M, 145
 - B89.1.13, 145
 - B89.1.14, 145
 - B89.1.17, 145
 - B89.3.1, 146
 - B89.3.4, 146
 - B89.3.7, 145
 - B89.4.10, 145
 - B89.4.19, 32, 145
 - B89.4.21.1, 146
 - B89.4.22, 145
 - B89.4.23, 146
 - B89.4.10360.2, 145
 - B89.6.2, 145
 - B89.7.1, 146
 - B89.7.2, 145
 - B89.7.3.1, 145
 - B89.7.3.2, 145
 - B89.7.3.3, 146
 - B89.7.4.1, 146
 - B89.7.5, 146
 - B89.7.6, 146
 - B89 REPORT, 146
 - PDS-1.1, 146
 - Assemblies:
 - tolerance in, 181–182, 183f, 184t
 - tolerance stack-up analysis in, 151
 - Assembly shift:
 - defined, 169
 - rules for, 169–171, 170f–171f
 - Asymmetric dimensional tolerance, worst-case
 - tolerance analysis in, 173, 173f, 173t
 - Atomic force microscopy (AFM), 16, 17
 - error budget table, 78t
 - error model, 88, 89, 93–96, 94f, 94t, 95f, 95t
 - Autocollimators, 281, 281f
 - Auxiliary dimensions, 157
 - Average of indirect measurements, standard
 - uncertainty and, 52–60
 - Avogadro's number, 9
 - Axis motion, budget of errors of, 240
- b**
- Ballbar, 24, 25f
 - Band chart, 45, 46t
 - Bar chart, 45, 46t
 - Bases, 42–43
 - Base units, *see* Primary/base SI units
 - Basic dimensions, 157
 - Bilateral tolerance, *see* Equal bilateral tolerance; Limit dimension
 - Bimetallic thermometer, 314–315, 315f
 - Binary base, 42–43
 - Block tolerances, 161, 161f
 - Bonus tolerance, 180
 - Bore gauge, 263, 264f
 - Bubble chart, 46t
- c**
- Calibration, 191–236
 - characteristics of, 193–195
 - accuracy ratio, 194
 - calibration range, 193
 - calibration tolerance, 193, 194

- instrument repeatability, 195
- reproducibility, 195
- span, 193
- static sensitivity, 193, 194f
- traceability, 194, 194f
- uncertainty, 194
- CNC machine tools:
 - contouring assessment using kinematic ballbar system, 219–221
 - error assessment and calibration, 207–219
 - inspection and positioning accuracy, 202, 204–206
 - 3-axis, 221–224
 - verification and calibration, 201–204, 203f, 204f
- coordinate measuring machine, 225–231
 - accreditation of calibration labs, 226–231, 227f–230f, 227t
 - performance verification, 225–226
- definition of, 191–192, 192f
- for dimensional measurement, *see* Dimensional measurements and calibration
- errors related to, 62, 66
- industry practices and regulations, 198–200, 200t
- laboratory requirements, 197–198
- and limitations of digital systems, 199, 201, 201f
- for mechanical measurement, 293–294. *See also* Mechanical measurements and calibration
- methods/procedures, 195–197, 196f
 - calibration procedure, 195–197
 - data calibration, 195
 - ISO 17025 calibration, 197
 - standard calibration, 195
- Michelson interferometry, 259–260, 260f, 260t
- need for, 192–193
- reporting measurement uncertainty in, 245
- tests for various test instruments, 231–234, 231t, 232t
- traceable, 10
- and uncertainty of measurement, 239
- Calibration laboratories:
 - accreditation, 226–231, 227f–230f, 227t
 - requirements, 197–198
- Calibration range, 193
- Calibration tolerance, 193, 194
- Calipers, 260, 260f
- Candela (cd), 4t, 6, 9
- Capacitance, in displacement measurement, 256–257, 257t
- CCD camera, edge detection using, 282–283, 282f, 283t
- Centi (c), 7t
- Certificates, reporting uncertainty in, 245, 247t
- Closed-loop data analysis, 350–352, 351f, 352f
- Cloud, data transfer to, 349, 350f
- CMMs, *see* Coordinate measuring machines
- CNC machine:
 - calibration, 221–224
 - contouring assessment using kinematic ballbar system, 219–221
 - error assessment and calibration, 207–219
 - example of calculations, 213, 215–219, 216f, 217t, 218f
 - experimental procedure, 208, 208f
 - nomenclature of measurement analysis variables, 209
 - performance criteria according to ISO standards, 210–213
 - tests and data acquisition, 213, 213t–215t
- inspection and positioning accuracy, 202, 204–206
- inspection of motion errors, 115, 116f–119f
- model of errors in, using HTM, 81–87
 - basic rotation matrices, 83, 84, 84f
 - basic translation matrices, 83, 83f
 - kinematic displacement of rigid body, 81–83, 82f
 - 3D axis machine case, 84–87, 87f
- 3-axis, 84–87, 87f, 221–224
- verification and calibration, 201–204, 203f, 204f
- Coincidence method of measurement, 106
- Comparison method of measurement, 106
- Compensation, for error elimination, 79–81, 81f

- Complementary method of measurement, 107
 - Complex geometric features, 282–284
 - edge detection using CCD camera, 282–283, 282*f*, 283*t*
 - full laser scanning for reverse engineering, 283, 284*f*
 - Composite method of measurement, 107
 - Compound tolerances, 161, 161*f*
 - Confidence intervals:
 - for large number of samples, 56, 58
 - for population, 54–56, 54*f*, 55*t*, 56*f*, 57*t*
 - for small number of samples on the unknown mean, 59–60, 60*t*
 - Conformity assessment, 11–12, 11*t*
 - Constants, 8–9
 - Contactless method of measurement, 107
 - Contact method of measurement, 107
 - Contouring assessment, using kinematic ballbar system, 219–221
 - Conversions:
 - angular, 44–45, 45*t*
 - Imperial/metric, 40–41, 40*t*–41*t*
 - of plus/minus dimensions and tolerances into equal-bilaterally toleranced dimensions, 165–167, 167*f*
 - pressure units, 311*t*
 - SI, 7–8, 7*t*
 - Coordinate measurement principle, 130–131, 131*f*
 - Coordinate measuring machines (CMMs), 24, 24*f*, 118–140
 - calibration, 225–231
 - accreditation of calibration labs, 226–231, 227*f*–230*f*, 227*t*
 - performance verification, 225–226
 - case studies, 135–140
 - CMM and digital inspection, 136–140, 137*f*, 138*t*–140*t*, 140*f*
 - CMM and reverse engineering, 135–136, 135*f*, 136*f*
 - coordinate measurement principle, 130–131, 131*f*
 - coordinate system and probing system, 121–127, 122*f*–125*f*, 127*f*–130*f*
 - description, 118, 120
 - inspection of motion errors in, 115
 - large-scale, 35
 - performance evaluation methods, 127, 128
 - qualification, 132–135
 - fast scans from reverse engineering, 134–135, 134*f*, 135*f*
 - full scanning, 132–134, 132*f*–134*f*
 - part-to-CAD inspection technique, 132
 - roundness measurement, 271, 272*f*
 - standards, 25–27
 - traceability of measurement, 11
 - types, 120–121, 121*f*, 121*t*
 - types of errors in, 129–130, 130*f*
 - Corrective action, 337
 - Coulomb (C), 5*t*
 - CPMS, *see* Cyber physical manufacturing systems
 - Current, SI unit of, 9
 - Cyber physical manufacturing systems (CPMS), 353–354, 354*f*
 - Cylinder chart, 46*t*
- d**
- Data acquisition (DAQ), 343–344, 343*f*, 344*t*
 - basic components of, 343, 343*t*
 - closed-loop data analysis (in-process inspection), 350–352, 351*f*, 352*f*
 - data transfer to cloud, 349, 350*f*
 - Internet of Things, 349, 350
 - length measurement in open loop, 344–345, 344*f*, 345*f*
 - setup fundamentals for, 344–352
 - thermal measurement, 345–349, 347*f*, 347*t*, 349*f*
 - Data acquisition errors, 66
 - Data calibration, 195
 - Data reduction errors, 66
 - Data transfer to cloud, 349, 350*f*
 - Deci (d), 7*t*
 - Decimal system, 42–43
 - Deflection method of measurement, 107
 - Degrees of freedom (d.o.f), 50, 243
 - Density measurement:
 - calibration of instruments, 307, 308
 - mechanical, 296, 298

- Depth gauge, 265, 265*f*
- Derived SI units, 3, 5*t*, 7
- Deterministic metrology, 1
- Dial gauge, 266–267, 266*f*
- Diameter measurement, 269, 269*f*, 270
- Differential or comparison method of measurement, 106
- Digital metrology, 341–355
 - calibration and limitations of systems, 199, 201, 201*f*
 - data acquisition, 343–344, 344*f*
 - basic components of, 343, 343*t*
 - measurement process, 343, 344*f*
 - setup fundamentals for, 344–352
 - digital devices, 109–110, 110*f*
 - digital twin metrology inspection, 352–354, 353*f*, 354*f*
 - implementation strategy, 343
 - setup fundamentals for, 344–352
 - closed-loop data analysis (in-process inspection), 350–352, 351*f*, 352*f*
 - data transfer to cloud, 349, 350*f*
 - Internet of Things, 349, 350
 - length measurement in open loop, 344–345, 344*f*, 345*f*
 - thermal measurement, 345–349, 347*f*, 347*t*, 349*f*
- Digital twin metrology inspection, 352–354, 353*f*, 354*f*
- Dimension(s), 2–3, 3*f*. *See also* Geometric dimensioning and tolerancing (GD&T)
 - definition of, 2
 - measuring, *see* Dimensional measurements and calibration
 - primary, 2
 - types of, 157–159, 157*f*–159*f*
 - auxiliary, 157
 - basic, 157
 - functional, 157
 - nonfunctional, 157
 - redundant, 157
 - reference, 157
- Dimensional measurements and calibration, 255–291
 - angles, 276–281
 - face standard devices, 277–279, 278*f*, 279*f*
 - incline measurement, 279–280, 279*f*, 280*f*
 - line standard devices, 277, 277*f*
 - optical instruments, 280–281, 281*f*
 - for complex geometric features, 282–284
 - edge detection using CCD camera, 282–283, 282*f*, 283*t*
 - full laser scanning for reverse engineering, 283, 284*f*
- diameter, 269, 269*f*, 270
- displacement, 255–260
 - capacitance, 256–257, 257*t*
 - laser measurements, 258
 - linear/rotative variable differential transformer, 257–258, 257*f*, 258*t*
 - Michelson interferometry, 258–260, 258*f*, 260*f*, 260*t*
- length, 255
- manual instruments, 260–268
 - American wire gauge, 263, 264*f*
 - angle plate, 265, 265*f*, 266
 - bore gauge, 263, 264*f*
 - calipers, 260, 260*f*
 - depth gauge, 265, 265*f*
 - dial gauge, 266–267, 266*f*
 - feeler gauge, 262, 262*f*
 - flat plate, 265*f*, 266
 - linear measurement tool, 263, 263*f*
 - micrometer, 262
 - oil gauging tapes, 267, 267*f*
 - planimeter, 267, 268*f*
 - telescopic feeler gauge, 264, 265*f*
 - thread measurement, 267, 268*f*
 - Vernier calipers, 261–262, 261*f*, 262*f*
- roundness, 269–276, 270*f*–275*f*, 274*t*, 276*t*
 - case study, 272–274, 273*f*, 274*f*, 274*t*
 - coordinate measuring machine, 271, 272*f*
 - in-process measurement, 274–276, 275*f*, 276*t*
 - rotational datum method, 271, 272, 272*f*
- surface texture, 285–291
 - geometry of surface, 285, 285*f*
 - roughness, 290–291, 290*f*, 291*f*
 - sampling length, 287–289, 288*f*, 288*t*
 - specification of surfaces, 286–287, 287*f*
 - surface integrity, 286

Direct method of measurement (DMM):
 definition of, 106
 formulation of mean and variance
 with, 49, 50

Displacement measurement, 255–260
 capacitance, 256–257, 257*t*
 laser measurements, 258
 linear/rotative variable differential
 transformer, 257–258, 257*f*, 258*t*
 Michelson interferometry, 258–260, 258*f*
 calibration, 259–260, 260*f*, 260*t*
 theory, 258, 259

Displaying devices, resolution of, 65

Distance, Imperial/metric conversions
 for, 40*t*

Distributions:

normal, 53–56, 54*f*, 55*t*, 56*f*, 57*t*
 Student's *t*-distribution, 55–56, 56*f*, 58–60

DMM, *see* Direct method of measurement

Donut/half-donut chart, 46*t*

Dynamic errors, 73, 74, 74*f*, 75*f*, 241

e

Edge detection using CCD camera, 282–283,
 282*f*, 283*t*

Electrical resistance thermometry, 315–316,
 316*f*

Electric capacitance (C/V), 5*t*

Electric charge (C), 5*t*

Electric conductance (A/V), 5*t*

Electric current, SI unit of, 4*t*

Electric resistance (V/A), 5*t*

Electromotive force (V), 5*t*

Element method of measurement, 107

Energy (Nm), 5*t*

Engineering metrology, 109

Engineering notation, 39–40

Enthalpy, 312

Environmental factors:

and random errors, 63
 as source of uncertainty, 239

Equal bilateral tolerance, 165*f*

converting plus/minus dimensions and
 tolerances into equal-bilaterally
 toleranced dimensions, 165–167, 167*f*

limit dimension to equal bilateral format,
 166

mean shift, 166, 167

unequal bilateral format to equal bilateral
 format, 166

unilaterally negative format to equal
 bilateral format, 166

unilaterally positive format to equal
 bilateral format, 166

definition of, 164

Equipment validation, 301–303

calibration vs., 303–304

features and benefits of, 302

need for, 302

process of, 302–303

Error(s), 61–97

in coordinate measuring machines, 129–130,
 130*f*

definition of, 61

dynamic, 74

error budget, 77–79

case study, 87–96

components of, 77

example of error-budget tables, 78–79, 78*t*,
 79*t*

error elimination techniques, 79–81

compensation, 79–81, 81*f*

error avoidance, 79

gross, 61

measurement, 63–69, 238–239

accuracy, 64

error of, 65

errors affecting accuracy, 240–241

error sources, 66

model of, 67–69, 68*f*, 69*f*

precision, 64

propagation of, 69–73

repeatability, 66–67, 66*f*

resolution, 64–65, 65*f*

static errors, 241

uncertainty, 66

measurement error, 66, 238–239

modeled in CNC using HTM, 81–87

basic rotation matrices, 83, 84, 84*f*

basic translation matrices, 83, 83*f*

- kinematic displacement of rigid body,
 - 81–83, 82*f*
 - 3D axis machine case, 84–87, 87*f*
 - motion error assessment, 63
 - propagation of, 69–73
 - quasi-static, 241
 - random, 63
 - definition of, 62
 - determining, 52, 53
 - in model of measurement, 67, 68*f*
 - in readings, 108
 - solved problems, 96–97, 96*t*
 - sources of, 73–76
 - Abbé error, 75–76, 76*f*
 - dynamic, 73, 74, 74*f*, 75*f*
 - measurement, 66
 - noise, 76, 76*f*
 - quasi-static, 74
 - random errors, 63
 - static, 73
 - systematic errors, 62
 - systematic, 62
 - definition of, 62
 - in model of measurement, 67, 68*f*
 - types, 61–63
 - random, 63
 - systematic, 62
 - user, 63
 - Error assessment and calibration (CNC machine tools), 207–219
 - Error avoidance, 79
 - Error budget, 77–79
 - case study, 87–96
 - description of designed system, 87–88, 88*f*
 - error modeling and experimental testing, 88–96, 90*f*–95*f*, 94*t*, 95*t*
 - components of, 77
 - example of error-budget tables, 78–79, 78*t*, 79*t*
 - uncertainty budget components, 240
 - Error-budget tables, 78–79, 78*t*, 79*t*
 - Error compensation, 79–81, 81*f*
 - active, 80
 - precalibrated, 80
 - Error elimination, 79–81
 - compensation, 79–81, 81*f*
 - error avoidance, 79
 - Error of measurement, 65
 - Exploded pie slice chart, 46*t*
 - Extrapolation method of measurement, 107
- f**
- Face standard angle measuring devices,
 - 277–279, 278*f*, 279*f*
 - angle gauges, 278, 279*f*
 - sine bar, 278, 278*f*
 - Farad (F), 5*t*
 - Feeler gauge, 262, 262*f*
 - Femto (f), 7*t*
 - Flat plate, 265*f*, 266
 - Flow rate (l/s), 5*t*
 - Force (N), 5*t*
 - Force calibration, 304
 - Force measurements, mechanical, 295, 296*f*, 297*f*
 - Fractional uncertainty, 247, 248*f*
 - Full laser scanning for reverse engineering,
 - 283, 284*f*
 - Full scanning (coordinate measuring machines), 132–134, 132*f*–134*f*
 - Functional dimensions, 157
 - Functional gap, stack-up analysis to secure,
 - 180–181, 180*f*, 181*f*
 - Fundamental method of measurement, 106
- g**
- Gas constants, 310–312
 - Gaussian distribution, 53
 - Geometric dimensioning and tolerancing (GD&T), 156–164
 - coordinate dimensioning, 158, 159*f*–160*f*, 160
 - dimension types, 157–158, 157*f*–159*f*
 - features of parts and their tolerances, 162–166, 162*f*–164*f*
 - notation and problem formation, 156
 - tolerance types, 160–161, 160*f*, 161*f*
 - block tolerances, 161, 161*f*
 - compound tolerances, 161, 161*f*

Geometric dimensioning and tolerancing (GD&T) (*contd.*)

- limit dimensions, 160, 160*f*, 161*f*
- plus and minus tolerances, 160
- when to use, 156

Geometric figures, 44, 44*f*

- areas, 44, 44*f*
- perimeter, 44, 44*f*
- volumes, 44, 44*f*

Geometry of surface, 285, 285*f*Giga (G), 7*t*

Global positioning systems (GPS), 36

- indoor, 36–37, 36*f*

Graphs, 45–46, 46*t*

Gravitational-based mass measurement

- instruments, 294

Gravitational interaction-based mass

- measurement instruments, 294

Gravitation constant, 8

Gross errors, 61

“Guide to the Expression of Uncertainty in Measurement”(GUM; JCGM 100:2008), 242, 244, 246

h

Hexadecimal base, 43

Homogeneous materials, law of, 322

Horizontal chart, 46*t*

Housekeeping practices, 338

Humidity, 312–313

Hydrometers, 297*f*, 298, 308

Hysteresis, 62

i

Ideal gas law, 310

IDM, *see* Indirect method of measurement

IEC 62622:2012(en), 20

Imperial unit system, 7

- Imperial/metric conversions, 40–41, 40*t*–41*t*

Incline measurement, 279–280, 279*f*, 280*f*

- inclinometer, 279–280, 279*f*, 280*f*
- spirit level, 279, 279*f*

Inclinometer, 279–280, 279*f*, 280*f*

Indirect method of measurement (IDM):

- definition of, 106

standard uncertainty and average with, 52–60

- determining measured value and random error, 52

normal distribution, 53–55, 54*f*, 55*t*

- repeated measurements of one single quantity, 52–53

Student's *t*-distribution, 55–56, 56*f*, 58–60, 58*f*Indoor GPS, 36–37, 36*f*

Industrial metrology, 1

Industry practices and regulations, for

- calibration, 198–200, 200*t*

In-process inspection, 350–352, 351*f*, 352*f*

Inspection:

CNC machines:

- motion errors, 115, 116*f*–119*f*
- positioning accuracy, 202, 204–206

coordinate measuring machines:

- and digital inspection, 136–140, 137*f*, 138*t*–140*t*

part-to-CAD technique, 132

digital twin metrology, 352–354, 353*f*, 354*f*in-process, 350–352, 351*f*, 352*f*

Installation qualification (IQ), 303

Instruments, 109–110

calibration of, *see* Calibrationdigital measuring devices, 109–110, 110*f*. *See also* Digital metrologydimensional measurement, *see* Dimensional measurements and calibrationlarge-scale metrology techniques, 34–37, 34*f*–36*f*macroscale metrology, 24, 24*f*, 25*f*mechanical measurement, *see* Mechanical measurements and calibration

metrological characteristics of, 108

nanometrology, 17, 18*t*

as source of uncertainty, 239

types, 109

Instrument drift, 62

Instrument range, 108

Instrument repeatability, 195

Intermediate metals, law of, 322

Intermediate temperatures, law of, 322, 323*f*

- International Prototype Meter bar, 5f, 6
- International standards, 142–145
- 4-ISO 17123-3:2001, 33–34
 - ISO 3:1973, 142
 - ISO 17:1973, 142
 - ISO 463:2006, 28
 - ISO 463:2006/Cor 1:2007, 28
 - ISO 463:2006/Cor 2:2009, 28
 - ISO 497:1973, 142–143
 - ISO 1502:1996, 28
 - ISO 2533:1975, 143
 - ISO 2533:1975/Add 1:1985, 143
 - ISO 2533:1975/Add 2:1997, 143
 - ISO 3274:1996, 28
 - ISO 3274:1996/Cor 1:1998, 28
 - ISO 3611:2010, 28
 - ISO 3650:1998, 28
 - ISO 3650:1998/Cor 1:2008, 28
 - ISO 5436-1:2000, 28
 - ISO 5436-2:2012, 28
 - ISO 5479:1997, 143
 - ISO 5725-1:1994, 143
 - ISO 5725-1:1994/Cor 1:1998, 143
 - ISO 5725-2:2019, 143
 - ISO 5725-3:1994, 143
 - ISO 5725-3:1994/Cor 1:2001, 143
 - ISO 5725-4:2020, 143
 - ISO 5725-5:1998, 144
 - ISO 5725-5:1998/Cor 1:2005, 144
 - ISO 5725-6:1994, 144
 - ISO 5725-6:1994/Cor 2001, 144
 - ISO 7863:1984, 28
 - ISO 8512-1:1990, 27
 - ISO 8512-2:1990, 27
 - ISO 9493:2010, 27
 - ISO 10012:2003, 144
 - ISO 10360, 225–226
 - ISO 10360-1:2000, 27
 - ISO 10360-1:2000/Cor 1:2002, 27
 - ISO 10360-2:2009, 27
 - ISO 10360-5:2020, 27
 - ISO 10360-6:2001, 27
 - ISO 10360-6:2001/Cor 1:2007, 27
 - ISO 10360-7:2011, 27
 - ISO 10360-8:2013, 27
 - ISO 10360-9:2013, 26
 - ISO 10360-10:2016, 26, 32–33
 - ISO 10360-12:2016, 26
 - ISO 11095:1996, 144
 - ISO 11843-1:1997, 144
 - ISO 11843-1:1997/Cor 1:2003, 144
 - ISO 11843-2:2000, 144
 - ISO 11843-2:2000/Cor 1:2007, 144
 - ISO 11843-3:2003, 144
 - ISO 11843-4:2003, 144
 - ISO 11843-5:2008, 144
 - ISO 11843-5:2008/Amd 1:2017, 144
 - ISO 11843-6:2019, 144
 - ISO 11843-7:2018, 144
 - ISO 11952:2019(en), 20
 - ISO 12179:2000, 26
 - ISO 12179:2000/Cor 1:2003, 26
 - ISO 13102:2012, 26
 - ISO 13225:2012, 26
 - ISO 13385-1:2019, 26
 - ISO 13385-2:2020, 25
 - ISO 14978:2018, 25
 - ISO 15189: 2012, 237
 - ISO 15530-3:2011, 25
 - ISO 16239:2013, 25
 - ISO 17025, 197
 - ISO 17025: 2017, 237–238
 - ISO 17123-1:2014, 33
 - ISO 21748:2017, 145
 - ISO 25178-601:2010(en), 21
 - ISO 25178-605:2014(en), 20–21
 - ISO/CD 3611, 28
 - ISO/CD 10360-11.2, 26
 - ISO/DIS 10360-10, 26
 - ISO/DIS 10360-13, 26
 - ISO/DIS 12179, 26
 - ISO/DIS 16269-3, 144
 - ISO/DIS 23131, 145
 - ISO/IEC 17025:2017 (E), 245
 - ISO/IEC Guide, 142–143
 - ISO/IEC/IEEE 15939:2017, 101–102
 - ISO symbols, 188
 - ISO/TR 18196:2016(en), 19
 - ISO/TR 21074:2016, 144
 - ISO/TR 22971:2005, 145

International standards (*contd.*)

- ISO/TS 15530-1:2013, 25
- ISO/TS 15530-4:2008, 25
- ISO/TS 17503:2015, 144
- ISO/TS 21749:2005, 145
- ISO/TS 23165:2006, 145
- ISO/TS 28038:2018, 145
- ISO/WD 5725-3, 143
- 3-ISO 17123, 33

International System of units (SI), 3–10

- classes of units, 3
- common measurements, 9–10
- definitions of main SI units, 4*t*, 6
- derived units, 5*t*, 7
- fundamental constants, 8–9
- International Prototype Meter bar, 5*f*, 6
- prefixes, 7–8, 7*t*
- primary/base units, 4, 4*f*, 4*t*
- primary/base units definitions, 6–7

Internet of Things (IoT), 349, 350

Interpolation method of measurement, 107

IoT (Internet of Things), 349, 350

IQ (installation qualification), 303

jJCGM 100:2008, *see* "Guide to the Expression of Uncertainty in Measurement"Joule (J), 5*t***k**Kelvin (K), 4*t*, 6, 9Kilo (k), 7*t*Kilogram (kg), 4*f*, 4*t*, 6, 9Kilogram per second (kg/s), 5*t*

Kinematic ballbar system, contouring assessment using, 219–221

l

Lab audits, 336

Lag time, 62

Large coordinate measuring machines, 35, 35*f*

- Large-scale metrology (LSM), 29–34, 30*f*
 - coordinate measuring machines, 35, 35*f*
 - definition of, 30
 - examples, 30–31, 31*f*

global positioning systems, 36

indoor GPS, 36–37, 36*f*industry need, 29, 29*f*instruments techniques, 34–37, 34*f*–36*f*

laser trackers, 35

theodolites, 35, 36*f*

verification standards, 32–35

Large-volume metrology (LVM), 29–30, 32, 37

Laser interferometry, 110–118, 111*f*–118*f*, 112*t*

definition of, 110–111

effects of environment on, 113–114, 114*t*inspection of motion errors, 115, 115*f*–118*f*

principles of measurement:

angles, 112, 113, 113*f*displacement, 111, 112*f*

linear position, 111

straightness, 112

Laser measurements, for displacement, 258

Laser trackers, 30–32, 30*f*, 31*f*, 35

Law of homogeneous materials, 322

Law of intermediate metals, 322

Law of intermediate temperatures, 322, 323*f*

Least material condition (LMC), 179

Legal metrology, 1

Length measurement:

of an arm, uncertainty on, 243

first measurements of, 3

large-scale, 31, 31*f*measuring, 255. *See also* Dimensional measurements and calibrationin open loop, 344–345, 344*f*, 345*f*Planck length (ℓ_p), 8–9SI unit of, 4*t*, 9

Light, SI unit of, 9

Limit dimension (bilateral tolerance), 160, 160*f*, 161*f*

converting to equal bilateral format, 166

tolerance format and decimal places, 164, 165*f*Linear interpolation, 42, 42*f*Linear measurement tool, 263, 263*f*

Linear motion inspection and positioning accuracy, 204–205

Linear variable differential transformer (LVDT), 257–258, 257*f*, 258*t*

- Line graph, 45, 46*t*
- Line standard angle measurement devices, 277, 277*f*
- Liquid-in-glass thermometer, 314
- Liter per second (1/s), 5*t*
- LMC (least material condition), 179
- Logarithmic Y-scale/pyramid chart, 46*t*
- LSM, *see* Large-scale metrology
- Luminous intensity, SI unit of, 4*t*
- LVDT, *see* Linear variable differential transformer
- LVM, *see* large-volume metrology
- m**
- Machine motion error assessment, 63
- Macroscale metrology, 23–28
- ballbar, 24, 25*f*
 - coordinate measuring machines, 24, 24*f*
 - standards, 25–28
- Manufactured products, motion error assessment for, 63
- Manufacturing considerations, 151–152, 152*f*
- Mass, 2
- first measurements of, 3
 - Imperial/metric conversions, 41*t*
 - Planck mass (m_p), 9
 - SI unit of, 4*f*, 4*t*, 9
- Mass calibration, 304
- Mass flow rate (kg/s), 5*t*
- Mass measurements, 294–295, 295*f*
- devices based on space linear acceleration mass, 295
 - gravitational-based instruments, 294
 - gravitational interaction-based instruments, 294
 - transducer-based measurements, 294
 - vibrating tube mass instrument, 295
- Master part tracking, 80
- Material condition modifiers (MCM), 178–187
- bonus tolerance, 180
 - gauging a pin with perpendicular callout, 180, 180*f*
 - least material condition, 179
 - maximum material condition, 178–180, 179*f*
 - regardless of feature size, 179, 179*f*
 - stack-up analysis to secure functional gap, 180–181, 180*f*, 181*f*
 - tolerance in assembly, 182, 183*f*, 184*t*
 - tolerance stack-up analysis, 182–187, 185*f*–187*f*
 - validating design and assembly, 181–182, 182*f*, 182*t*
- Math, applied, *see* Applied math and statistics
- Maximum material condition (MMC), 178–180, 179*f*
- MCM, *see* Material condition modifiers
- Mean:
- arithmetic, and type A uncertainty, 242
 - based on samples, 50
 - for direct measurements, 49, 50
 - standard deviation of, 51, 51*f*
 - unknown, confidence intervals for small number of samples on, 59–60, 60*t*
- Mean shift calculation, 166, 167
- Measured value, determining, 52, 53
- Measurement analysis, nomenclature of variables used in, 209
- Measurement and measurement systems, 99–147. *See also* International System of units (SI)
- accreditation and conformity assessment, 11–12, 11*t*
 - chains of comparisons in, 100, 100*f*
 - common, 9–10
 - components of, 238
 - conversions among, *see* Conversions
 - definition of, 1, 103, 105
 - definitions of key measurement components, 102–103
 - measurement process, 103
 - measurement system, 102
 - measurement system analysis, 103
- differences between number and an analysis model, 104–105
- digital measuring devices, 109–110, 110*f*. *See also* Digital metrology
- dimension, 2–3, 3*f*. *See also* Dimensional measurements and calibration
- direct measurement, 49, 50, 106

- Measurement and measurement systems
(*contd.*)
- and error:
 - error sources, 66
 - measurement repeatability, 67
 - model of, 67–69, 68*f*, 69*f*
 - precision, 64
 - repeatability, 66–67, 66*f*
 - resolution, 64–65, 65*f*
 - uncertainty, 66
 - indirect measurement, 52–60, 102
 - instrumentation for measurement, 109–110.
 - See also* Instruments
 - measurement error, 238–239
 - measurement methods, 105–108
 - metrological characteristics of measuring instruments, 108
 - metrology and measurement, 105–107
 - measurement process, 2, 2*f*, 100, 100*f*, 103
 - definition of, 103
 - ISO/IEC/IEEE 15939:2017 on, 101–102
 - as source of uncertainty, 239
 - measurement systems, 3, 99–100, 100*f*
 - accuracy of, 64
 - definition of, 102
 - models of, 100
 - purpose of, 99
 - resolution of, 64
 - measurement system analysis, 103
 - metrology laboratory test for students, 140–142, 141*f*, 142*f*
 - non-portable dimensional measuring devices, 110–140
 - coordinate measuring machine, 118–140, 119*f*, 121*f*–125*f*, 121*t*–123*t*, 127*f*–137*f*, 138*t*–140*t*
 - laser interferometry, 110–118, 111*f*–118*f*, 112*t*
 - NPL guiding principles for, 99
 - physical measurement process, 103–104, 104*f*
 - repeated, of one single quantity, 52–53
 - standards for:
 - ASME, 145–146
 - international, 101–102, 142–145
 - ISO/IEC/IEEE 15939:2017 standard, 101–102
 - statistical, 47
 - statistical analysis of, 47–48
 - traceability of, 10–12, 100
 - uncertainty in, 10, 238. *See also* Uncertainty, in measurement
 - Measurement data, 47
 - Measurement error, 66, 238–239
 - Measurement process, 100, 100*f*
 - definition of, 103
 - ISO/IEC/IEEE 15939:2017 on, 101–102
 - as source of uncertainty, 239
 - Measurement repeatability (repeatability), 66–67
 - definition of, 67
 - and repeatability of measurement, 66
 - Measurement systems, 3, 99–100, 100*f*. *See also* Measurement and measurement systems
 - accuracy of, 64
 - definition of, 102
 - models of, 100
 - purpose of, 99
 - resolution of, 64
 - Measurement system analysis, 103
 - Measurement uncertainty, 10
 - Measuring force, 108
 - Mechanical measurements and calibration, 293–308
 - acoustic measurements, 298–300, 299*f*, 300*f*
 - calibration of instruments, 300–301, 304–308
 - acoustic measurements, 308
 - force calibration, 304
 - hydrometers, 308
 - mass calibration, 304
 - need for, 300–301
 - pressure calibration, 304–306
 - process of, 301
 - validation of equipment vs., 303–304
 - vibration measurements, 306–307, 307*t*, 308*f*
 - volume and density, 307, 308
 - equipment validation, 301–303
 - calibration vs., 303–304

- features and benefits of, 302
 - need for, 302
 - process of, 302–303
 - force measurements, 295, 296*f*, 297*f*
 - hydrometers, 297*f*, 298
 - importance of, 293
 - mass measurements, 294–295, 295*f*
 - devices based on space linear acceleration mass, 295
 - gravitational-based instruments, 294
 - gravitational interaction-based instruments, 294
 - transducer-based measurements, 294
 - vibrating tube mass instrument, 295
 - mechanical calibration, 293–294
 - vibration measurements, 294, 296
 - volume and density measurement, 296, 298
 - Mega (M), 7*t*
 - Meter (m), 4*t*, 6, 9
 - Meter per second (m/s), 5*t*
 - Metric system, Imperial conversions with, 40–41, 40*t*–41*t*
 - Metrology, 1–2, 2*f*
 - definition of, 105
 - functions and objectives, 1
 - and measurement, 105–107
 - measurement and quantification in, 99
 - process of measurement, 2, 2*f*
 - types of, 1
 - Metrology laboratory test for students, 140–142, 141*f*, 142*f*
 - Michelson interferometer, 111*f*
 - displacement measurement, 258–260, 258*f*
 - calibration, 259–260, 260*f*, 260*t*
 - theory, 258, 259
 - principle of, 115, 116*f*–117*f*
 - Micro (μ), 7*t*
 - Micrometer, 262
 - Micrometrology, 22–23
 - definition of, 22
 - examples, 22, 22*f*, 23*f*
 - industry need, 22
 - Milli (m), 7*t*
 - Missing factors, 62
 - MMC (maximum material condition), 178–180, 179*f*
 - Mole (mol), 4*t*, 6, 9
 - Motion error assessment, 63
 - Motion error inspection (coordinate measuring machines), 115
 - Multi-junction thermocouple circuits, 326, 326*f*
 - Multi-pane chart, 45, 46*t*
- n**
- Nano (n), 7*t*
 - Nanometrology, 14–18
 - definition of, 15
 - examples, 16–17, 16*f*, 17*f*
 - importance of, 15–16
 - industry need, 14–15
 - instruments and resolution ranges, 17, 18*t*
 - standards, 18–21
 - Nanotechnology standards, 18–21
 - Newton (N), 5*t*
 - Noise, 76, 76*f*
 - Nonfunctional dimensions, 157
 - Non-portable dimensional measuring devices, 110–140
 - coordinate measuring machine, 118–140, 119*f*, 121*f*–125*f*, 121*t*–123*t*, 127*f*–137*f*, 138*t*–140*t*
 - laser interferometry, 110–118, 111*f*–118*f*, 112*t*
 - Normal distribution, 53–56, 54*f*, 55*t*, 56*f*, 57*t*
 - Null method of measurement, 107
 - Numbers:
 - bases, 42–43
 - differences between an analysis model and, 104–105
- o**
- Occupational safety (OS), 337–338
 - OHLC chart, 45, 46*t*
 - Ohm (Ω), 5*t*
 - Oil gauging tapes, 267, 267*f*
 - Operation qualification (OQ), 303
 - Operators, as source of uncertainty, 239
 - Optical angle comparators, 280–281, 281*f*

Optical angle measurement instruments,
280–281, 281*f*
autocollimators, 281, 281*f*
optical angle comparators, 280–281, 281*f*
OQ (operation qualification), 303
OS (occupational safety), 337–338

p

Parallax, 108
Parallax factor, 63
Parametric error measurement, 80
Part-to-CAD inspection technique (coordinate measuring machines), 132
Pascal (Pa), 5*t*
PDF (probability density function), 54
Peltier effect, 322
Performance evaluation methods (coordinate measuring machines), 127, 128
Performance qualification (PQ), 303
Performance verification (coordinate measuring machines), 225–226
Perimeter, 44, 44*f*
Physical measurement process (PMP), 103–104, 104*f*
Physical variations, random errors and, 63
Pico (p), 7*t*
Planck length (ℓ_p), 8–9
Planck mass (m_p), 9
Planck's constant, 8–9
Planck time (t_p), 9
Planimeter, 267, 268*f*
Plots, 45–46, 46*t*
PMP (physical measurement process), 103–104, 104*f*
Population, 49, 49*f*
confidence intervals, 54–56, 54*f*, 55*t*, 56*f*, 57*t*
definition of, 49
Positioning accuracy (CNC machine tools), 202, 204–206
Power (J/s), 5*t*, 312
PQ (performance qualification), 303
Precalibrated error compensation, 80
Precision errors, 52
Precision of measurement, 2, 64

Pressure (N/m²), 5*t*
Pressure calibration, 304–306
Preventive action, 336
Primary/base SI units, 3, 4, 4*f*, 4*t*
definitions, 6–7
and derived units, 5*t*
Probability, 48
Probability density function (PDF), 54
Propagation of errors, 69–73
Protractor, 277, 277*f*

q

QA (quality assurance), 335, 335*f*
QC (quality control), 335, 335*f*
QS, *see* Quality system
Quality assessment, 335, 336
Quality assurance (QA), 335, 335*f*
Quality audits, 336, 337*f*
Quality control (QC), 335, 335*f*
Quality management, 331–339
components of, 334–336
quality assessment, 335, 336
quality assurance, 335, 335*f*
quality control, 335, 335*f*
quality system, 334, 335*f*
ISO-based QMS certification, 333, 334, 334*t*
quality management system, 333
quality standards and guides, 333–334, 333*f*, 334*t*, 338–339
system components, 336–338
corrective action, 337
housekeeping practices, 338
occupational safety requirements, 337–338
preventive action, 336
quality audits, 336, 337*f*
total quality management, 332, 333
Quality management system (QMS), 333, 334, 334*t*
Quality system (QS), 334, 335*f*
components of, 336–338
QMS, 333
quality standards and guides, 338–339
Quantity of heat (N/m), 5*t*
Quasi-static errors, 74, 241

r

- R (reference point), 75
- Radian per second (1/s), 5*t*
- Radiative temperature measurement, 327–329, 328*f*, 329*f*
- Random errors:
 - definition of, 62
 - determining, 52, 53
 - in model of measurement, 67, 68*f*
 - sources of, 63
- Range:
 - calibration, 193
 - instrument, 108
 - measurement, 108
 - scale, 108
- Ratio, 41
- Reading accuracy, 108
- Reading error, 108
- Reduced Planck's constant, 8, 9
- Redundant dimensions, 157
- Reference dimensions, 157
- Reference point (R), 75
- Regardless of feature size (RFS), 179, 179*f*
- Relative uncertainty, 248
- Repeatability:
 - definition of, 67, 108
 - instrument, 195
 - measurement, 67
 - of measurement, 2, 66
- Repeated measurements, of one single quantity, 52–53
- Reporting uncertainty, 243–247, 247*t*
 - process for, 245–247, 247*t*
 - requirements for, 243–245
- Reproducibility, 195
- Resistance temperature detectors, 316–320, 317*f*, 318*f*
- Resolution, 64–65, 65*f*
 - definition of, 64
 - of a displaying device, 65
 - of a measuring system, 64
 - and random errors, 63
- Reverse engineering:
 - CMM fast scans from, 134–135, 134*f*, 135*f*
 - full laser scanning for, 283, 284*f*
 - RFS (regardless of feature size), 179, 179*f*
 - Root-sum squared (RSS) statistical analysis, worst-case analysis vs., 175–176
 - Rotary table:
 - error budget table, 78*t*
 - error modeling of, 91–93, 92*f*, 93*f*
 - inspection and positioning accuracy, 205–206
 - Rotational datum method, for roundness, 271, 272, 272*f*
 - Rotative variable differential transformer (RVDT), 257, 258, 258*t*
 - Roughness measurement, 290–291, 290*f*, 291*f*
 - Rounding, 43
 - Roundness measurement, 269–276, 270*f*–275*f*, 274*t*, 276*t*
 - case study, 272–274, 273*f*, 274*f*, 274*t*
 - coordinate measuring machine, 271, 272*f*
 - in-process measurement, 274–276, 275*f*, 276*t*
 - rotational datum method, 271, 272, 272*f*
 - RSS (root-sum squared) statistical analysis, worst-case analysis vs., 175–176
 - RVDT, *see* Rotative variable differential transformer

s

 - Sample(s), 49, 49*f*
 - confidence intervals for large number of, 56, 58
 - confidence intervals for small number of, 59–60, 60*t*
 - mean and variance based on, 50
 - Sampling:
 - reporting measurement uncertainty when reporting, 245
 - as source of uncertainty, 239
 - Sampling length:
 - definition of, 287
 - surface texture measurement, 287–289, 288*f*, 288*t*
 - Scales, 13–37, 14*f*
 - large-scale metrology and large-volume metrology, 29–34
 - coordinate measuring machines, 35
 - definition of, 30

Scales (*contd.*)

examples, 30–31, 31*f*
 industry need, 29, 29*f*
 instruments techniques, 34–37, 34*f*–36*f*
 verification standards, 32–35
 macroscale metrology, 23–28, 24*f*, 25*f*
 ballbar, 24, 25*f*
 coordinate measuring machines, 24, 24*f*
 standards, 25–28
 micrometrology, 22–23
 definition of, 22
 examples, 22, 22*f*, 23*f*
 industry need, 22
 nanometrology, 14–18
 definition of, 15
 examples, 16–17, 16*f*, 17*f*
 importance of, 15–16
 industry need, 14–15
 instruments and resolution ranges, 17, 18*t*
 standards, 18–21
 Scale division value, 108
 Scale range, 108
 Scale spacing, 108
 Scanning-probe microscopes (SPMs):
 images from, 16, 16*f*–17*f*
 standards, 20
 Scientific metrology, 1
 Scientific notation, 39
 Screwdriver calibration, 304
 Second (s), 4*t*, 6, 9
 Seebeck effect, 322
 Sensing point (S), 75
 Sensitivity (amplification or gearing ratio), 108
 Sensitivity threshold, 108
 SI conversions, 7–8, 7*t*
 Siemens (S), 5*t*
 Significant digits, 43
 Sine bar, 278, 278*f*
 SI units, *see* International System of units (SI)
 Space linear acceleration mass, devices based
 on, 295
 Span, 193
 Speed of light, 8
 Spicer chart, 45, 46*t*
 Spirit level, 279, 279*f*

SPMs, *see* Scanning-probe microscopes

Stacked bar chart, 46*t*

Standards:

ASME, 145–146. *See also* ASME standards
 definition of, 18
 international, 142–145. *See also*
 International standards
 large-scale metrology verification, 32–35
 macroscale metrology, 25–28
 measurement, 101–102
 nanometrology, 18–21
 quality, 333–334, 333*f*, 334*t*, 338–339
 Standard acceleration for gravity, 9
 Standard calibration, 195
 Standard deviation:
 of the mean, 51, 51*f*
 and type A uncertainty, 243
 Standard uncertainty, 52–60
 determining measured value and random
 error, 52
 normal distribution, 53–55, 54*f*, 55*t*
 repeated measurements of one single
 quantity, 52–53
 Student's *t*-distribution, 55–56, 56*f*, 58–60,
 58*f*
 Static errors, 73, 241
 Static sensitivity, 193, 194*f*
 Statistics, *see* Applied math and statistics
 Statistical analysis:
 and common distributions, 47–52
 definition of measurement data, 47
 formulation of mean and variance for
 direct measurements, 49, 50
 mean and variance based on samples, 50
 of measurements, 47–48
 probability, 48
 sample and population, 49, 49*f*
 standard deviation of the mean, 51, 51*f*
 statistical measurements, 47–48
 of measurements, 47–48
 Statistical tolerance analysis, 173–187
 case discussions, 176–178, 176*f*–178*f*
 definition of, 173–175, 174*f*, 175*t*
 material condition modifiers, 178–187
 bonus tolerance, 180

- gauging a pin with perpendicular callout, 180, 180*f*
- least material condition, 179
- maximum material condition, 178–179, 179*f*
- regardless of feature size, 179, 179*f*
- stack-up analysis to secure functional gap, 180–181, 180*f*, 181*f*
- tolerance in assembly, 182, 183*f*, 184*t*
- tolerance stack-up analysis, 182–187, 185*f*–187*f*
- validating design and assembly, 181–182, 182*f*, 182*t*
- second-order tolerance analysis, 176
- worst-case analysis vs. RSS statistical analysis, 175–176
- Stress (N/m^2), 5*t*
- Student's *t*-distribution, 55–56, 56*f*, 58–60
- Substitution method of measurement, 106
- Surface(s), specification of, 286–287, 287*f*
- Surface finish characterization, 289
- Surface integrity, 286
- Surface texture measurement, 285–291
 - geometry of surface, 285, 285*f*
 - roughness, 290–291, 290*f*, 291*f*
 - sampling length, 287–289, 288*f*, 288*t*
 - control parameters, 288, 289*f*
 - filters, 288, 288*f*
 - surface finish characterization, 289
 - specification of surfaces, 286–287, 287*f*
 - surface integrity, 286
- Symmetric dimensional tolerance, worst-case tolerance analysis in, 171–172, 172*f*
- Systematic errors, 62
 - definition of, 62
 - in model of measurement, 67, 68*f*
- t**
- T*-distribution, Student's, 55–56, 56*f*, 58–60
- Technical drawings, 152–153, 153*f*, 154*f*
- Telescopic feeler gauge, 264, 265*f*
- Temperature:
 - measuring:
 - digital measurement and data acquisition, 345–349, 347*f*, 347*t*, 349*f*
 - methods of, 313–314
 - radiative temperature, 327–329, 328*f*, 329*f*
 - scale of, 309–312, 311*t*
 - scale of:
 - gas constants, 310–312
 - ideal gas law, 310
 - vacuum, 310, 311*t*
 - SI unit of, 9
- Tests and testing:
 - reporting uncertainty in, 245
 - and uncertainty of measurement, 239
- Theodolites, 33–35, 36*f*
- Thermal expansion materials, thermodynamic measurement through, 314–321
 - bimetallic thermometer, 314–315, 315*f*
 - electrical resistance thermometry, 315–316, 316*f*
 - liquid-in-glass thermometer, 314
 - resistance temperature detectors, 316–320, 317*f*, 318*f*
 - thermistors, 320, 321*f*
- Thermistors, 320, 321*f*
- Thermocouples, 321–326
 - basic, 321–322, 321*f*
 - fundamental laws for, 322–323, 323*f*
 - materials for, 323–326, 324*t*
 - advantages and disadvantages of, 324–325
 - voltage measurement, 325–326
 - multi-junction thermocouple circuits, 326, 326*f*
 - voltage measurement, 325–326
- Thermodynamic measurements, 309–329
 - enthalpy, 312
 - humidity, 312–313
 - power, 312
 - temperature:
 - methods of measuring, 313–314
 - radiative temperature, 327–329, 328*f*, 329*f*
 - scale of, 309–312, 311*t*
 - thermocouple materials, 323–326, 324*t*
 - advantages and disadvantages of, 324–325
 - voltage measurement, 325–326
 - thermoelectric, or thermocouples, 321–326

Thermodynamic measurements (*contd.*)
 basic thermocouples, 321–322, 321*f*
 fundamental thermocouple laws, 322–323, 323*f*
 materials for thermocouples, 323–326, 324*t*
 multi-junction thermocouple circuits, 326, 326*f*
 voltage measurement, 325–326
 thermopiles, 327, 327*f*
 through thermal expansion materials, 314–321
 bimetallic thermometer, 314–315, 315*f*
 electrical resistance thermometry, 315–316, 316*f*
 liquid-in-glass thermometer, 314
 resistance temperature detectors, 316–320, 317*f*, 318*f*
 thermistors, 320, 321*f*

Thermodynamic temperature, SI unit of, 4*t*

Thermopiles, 327, 327*f*

Thomson effect, 322

Thread measurement, 267, 268*f*

3-axis CNC machine, 84–87, 87*f*, 221–224
 calibration, 221–224
 error modeling:
 of nanomanipulator arm, 89–91, 90*f*, 91*f*
 using HTM, 84–87, 87*f*

Time:
 first measurements of, 3
 Planck time (t_p), 9
 SI unit of, 4*t*, 9

Tolerance:
 calibration, 193, 194
 formats and decimal places, 164–165, 165*f*
 bilateral tolerance (limit dimension), 164, 165*f*
 equal bilateral tolerance, 164, 165*f*
 unequal bilateral tolerance, 165, 165*f*
 unilateral tolerance, 165, 165*f*
 and uncertainty of measurement, 239

Tolerance build-up, 168, 168*f*

Tolerance stack-up analysis, 149–187
 in assemblies, 151
 benefits of, 168

converting plus/minus dimensions and tolerances into equal-bilaterally tolerated dimensions, 165–167, 167*f*
 limit dimension to equal bilateral format, 166
 mean shift, 166, 167
 unequal bilateral format to equal bilateral format, 166
 unilaterally negative format to equal bilateral format, 166
 unilaterally positive format to equal bilateral format, 166

definition of, 167

definitions and format in, 153, 154

geometric dimensioning and tolerancing, 156–164
 coordinate dimensioning, 158, 159*f*–160*f*, 160
 dimension types, 157–158, 157*f*–159*f*
 features of parts and their tolerances, 162–166, 162*f*–164*f*
 notation and problem formation, 156
 tolerance types, 160–161, 160*f*, 161*f*
 when to use, 156

importance of, 149–150

ISO and ASME Y14 symbols, 188

manufacturing considerations in engineering design, 151–152, 152*f*
 need for, 150–151, 167
 reasons for using, 150–151, 167

statistical tolerance analysis, 173–187
 cases discussions, 176–178, 176*f*–178*f*
 definition of, 173–175, 174*f*, 175*t*
 material condition modifiers, 178–187
 second-order tolerance analysis, 176
 worst-case analysis vs. RSS statistical analysis, 175–176

technical drawings, 152–153, 153*f*, 154*f*

tolerance build-up, 168, 168*f*

tolerance formats and decimal places, 164–165, 165*f*
 bilateral tolerance (limit dimension), 164, 165*f*
 equal bilateral tolerance, 164, 165*f*

- unequal bilateral tolerance, 165, 165*f*
 - unilateral tolerance, 165, 165*f*
 - workflow of, 154–156, 155*f*
 - worst-case tolerance analysis, 169–173
 - assembly shift, 169–171, 170*f*–171*f*
 - in asymmetric dimensional tolerance, 173, 173*f*, 173*t*
 - in symmetric dimensional tolerance, 171–172, 172*f*, 172*t*
 - Torque wrench calibration, 304
 - Total quality management (TQM), 332, 333
 - Traceability, 2, 10–12, 100
 - accreditation and conformity assessment, 11–12, 11*t*
 - in calibration, 194, 194*f*
 - definition of, 10
 - example, 11
 - Traceability chain, 10, 11
 - Transducer-based mass measurements, 294
 - Transposition method of measurement, 106
 - Truncation, 43
 - Type A uncertainty, 241–243, 248*f*
 - Type B uncertainty, 241–243
- u**
- Uncertainty:
 - in calibration, 194
 - fractional, 247, 248*f*
 - in measurement, 10, 237–253
 - causes of, 239–240
 - and components of measurement, 238
 - dynamic errors, 241
 - errors affecting accuracy, 240–241
 - as error source, 66
 - evaluations and analysis of, 242–245
 - fractional uncertainty, 247, 248*f*
 - importance of, 239
 - ISO 15189: 2012 requirements, 237
 - ISO 17025: 2017 requirements, 237–238
 - measurement error, 238–239
 - and propagation of errors, 69–73
 - propagation of uncertainty, 247–252, 250*f*
 - quasi-static errors, 241
 - reporting, 243–247, 247*t*
 - standard, and average of indirect measurements, 52–60
 - static errors, 241
 - types A and B of uncertainty, 241–243, 248*f*
 - uncertainty budget components, 240
 - relative, 248
 - reporting, 243–247, 247*t*
 - process for, 245–247, 247*t*
 - requirements for, 243–245
 - types A and B, 241–243
 - Uncertainty budget components, 240
 - Unequal bilateral tolerance, 165, 165*f*, 166
 - Unilaterally negative format, converting to equal bilateral format, 166
 - Unilaterally positive format, converting to equal bilateral format, 166
 - Unilateral tolerance, 165, 165*f*
 - Units of measurement, 2–6, 3*f*. *See also* International System of units (SI)
 - User error, 63
- v**
- Vacuum measurement, 310, 311*t*
 - Variance:
 - based on samples, 50
 - for direct measurements, 49, 50
 - Velocity (m/s), 5*t*
 - Verification:
 - CNC machine tools, 201–204, 203*f*, 204*f*
 - coordinate measuring machines, 225–226
 - large-scale metrology standards, 32–35
 - Vernier calipers, 261–262, 261*f*, 262*f*
 - Vibrating tube mass instrument, 295
 - Vibration measurements:
 - calibration of instruments, 306–307, 307*t*, 308*f*
 - mechanical, 294, 296
 - Volt (V), 5*t*
 - Voltage measurement, 325–326

Volume measurement, 44, 44*f*
 calibration of instruments, 307, 308
 first measurements, 3
 mechanical, 296, 298

W

Watt (W), 5*t*
Work (Nm), 5*t*

Worst-case (WC) tolerance analysis, 169–173
 assembly shift, 169–171, 170*f*–171*f*
 in asymmetric dimensional tolerance, 173,
 173*f*, 173*t*
 RSS (root-sum squared) statistical analysis
 vs., 175–176
 in symmetric dimensional tolerance,
 171–172, 172*f*, 172*t*