

# Erratum: “A Design and Rating Method for Shell-and-Tube Heat Exchangers with Helical Baffles” [ASME J. Heat Transfer, 2010, 132(5), p. 051802]

J. F. Zhang, Y. L. He, and W. Q. Tao

---

There are some errors in Eq. (22), Table 1, and nomenclature. The corrections of these errors are shown below:

(1)

$$S_{2z} = 0.5(B - S_p / \cos \beta) \left[ D_1 - D_s + \frac{D_s - d_o}{t_t} (t_t - d_o) \right] \quad (22)$$

(2)  $D_o/D_i$  in Table 1 should be  $D_o/D_1$ .

(3)  $D_{cut}$  in the nomenclature should be deleted and following revisions should be made:

$D_1$  = inside diameter of the shell, m.

$D_o$  = outside diameter of the shell, m.

$D_s$  = diameter of the tube bundle, m.