

# ERRATA

An errata on the paper by O. Pinkus and S. S. Bupara, "Analysis of Misaligned Groove Journal Bearings," published in the October, 1979 issue of the JOURNAL OF LUBRICATION TECHNOLOGY, Vol. 101, pp. 503-509.

In the above paper all tabulated values of  $\bar{\delta}$  should be divided by two.