

Erratum: “A Four Degree of Freedom Robot for Positioning Ultrasound Imaging Catheters” [J. Mechanisms Robotics 8(5), 051016 (May 04, 2016); DOI: 10.1115/1.4032249]

The incorrect version of Fig. 15 was published with text missing in control flow boxes. The corrected diagram is given below.

